
Installation Guide

After installing the USB driver it is necessary to copy the following files into the folder indicated for the correct functioning of the key.

32-bit systems

ETS3 or 4: transfer files within the ZIP archive to the specified folder:

C: \ Program Files \ Common Files \ EIBA sc \ Falcon \ USB



ETS5: transfer the file in the ZIP archive to the specified folder:

C: \ Program Files (x86) \ ETS5


C: \ ProgramData \ KNX \ Falcon



64-bit systems

ETS3 / 4: transfer the file within the ZIP archive to the specified folder:

C: \ Program Files (x86) \ Common Files \ EIBA sc \ Falcon \ USB



ETS5: transfer the file in the ZIP archive to the specified folder:

C: \ Program Files (x86) \ ETS5

C: \ ProgramData \ KNX \ Falcon

